


PARTS LIST & PARTS LIST

70-1420VSR HEADSTOCK ASSEMBLY SHEET B



NOTE: Please reference the Part Number when calling for Replacement Parts.

For Parts under Warranty, the Serial Number of your machine is required.

KEY NO.	DESCRIPTION	QTY	PART NO.	KEY NO.	DESCRIPTION	QTY	PART NO.
1	Spur center	1	70-943	21	Standard spring washer 6	4	P70-1420VSR-21B
2	Hex cup point screw M6x8	4	P70-1420VSR-2B	22	Hex cup point screw M8x6	4	P70-1420VSR-22B
3	3-3/8" Faceplate	1	70-933	23	Hex cup point screw M8x10	2	P70-1420VSR-23B
4	Spindle	1	P70-1420VSR-4B	24	Spindle pulley	1	P70-1420VSR-24B
5	Hex socket screw M5x12	3	P70-1420VSR-5B	25	Spacer	1	P70-1420VSR-25B
6	Bearing end cap/plate	1	P70-1420VSR-6B	26	Washer	1	P70-1420VSR-26B
7	Bearing 6007	2	P70-1420VSR-7B	27	Locking nut	1	P70-1420VSR-27B
8	Corrugated gasket	1	P70-1420VSR-8B	28	Wheel	1	P70-1420VSR-28B
9	Magnet sleeve	1	P70-1420VSR-9B	29	Poly-V-belt	1	70-985
10	Magnet	2	P70-1420VSR-10B	30	Side panel	1	P70-1420VSR-30B
11	Tapping screw ST3x6	2	P70-1420VSR-11B	31	Tachymeter head	1	P70-1420VSR-31B
12	Hinge shaft	1	P70-1420VSR-12B	32	Hex socket screw M5x8	1	P70-1420VSR-32B
13	Hex lock nut M5	1	P70-1420VSR-13B	33	Cable plate	1	P70-1420VSR-33B
14	Headstock cover	1	P70-1420VSR-14B	34	Plate	1	P70-1420VSR-34B
15	Panels	1	P70-1420VSR-15B	35	Hex socket screw M3x10	2	P70-1420VSR-35B
16	Hex socket screw M5x12	1	P70-1420VSR-16B	36	Flat washer 6	4	P70-1420VSR-36B
17	Pan head screw M4x10	3	P70-1420VSR-17B	37	Headstock	1	P70-1420VSR-37B
18	Flat washer 4	3	P70-1420VSR-18B	38	Hex socket screw M4x12	4	P70-1420VSR-38B
19	Hinge	1	P70-1420VSR-19B	39	Stop pin assembly	1	P70-1420VSR-39B
20	Hex cap screw M6x30	4	P70-1420VSR-20B				